REAR MATRIX SITS BEHIND 2 LUGS AND FLAT ON BASE SEE BELOW

GEM LOOSE COAL SET UP



FRONT FIBRE SITS IN WELL OF BURNER AS ABOVE



FRONT 4 LOOSE COALS SIT AS ABOVE



NEXT SET OF 3 FIT AS SHOWN ABOVE WITH THE LEFT AND RIGHT HAVING THE POINT OF THE COAL POINTING OUTWARDS



NEXT 2 SIT AS ABOVE AGAIN WITH THE POINTS OF THE COALS LOOKING OUTWARDS



FINAL 3 SIT CENTRALLY ON TOP AS ABOVE